




TWO-BOLT METHOD (PREFERRED)




ONE-BOLT METHOD



MULTIPLE SPANS



COMMUNICATIONS CABLE AT INTERMEDIATE POLE



NOTE

FOR CONNECTING MESSENGER TO MESSENGER, USE BURNDY CLAMP (UCG25RS), 3-BOLT CLAMP OR EQUIVALENT. FOR CONNECTING COPPER WIRE TO MESSENGER, USE BURNDY CLAMP (UCG25RS) OR EQUIVALENT.